



Town of Halifax
Board of Health
Supplementary Rules and Regulations to the
State Environmental Code: Title V,
310 CMR 15.00

Adopted: November 12, 2004.

Revised: December 01, 2004.

Revised: August 19, 2015.

Revised: December 09, 2020.

Amended: December 09, 2020. **Effective:** January 01, 2021.

Revised: February 17, 2021.



TOWN OF HALIFAX COMMONWEALTH OF MASSACHUSETTS

Board of Health

499 Plymouth St., Halifax, MA 02338
*Telephone (781) 293 6768 *Fax (781) 293 1738

Supplementary Rules and Regulations to the State Environmental Code: Title 5, 310 CMR 15,000

“Standard Requirements for the siting, construction, inspection, upgrade and expansion of on-site sewage treatment and disposal systems.”

1.09 Septic System Title V Inspections

- (1) Mandate Soil Evaluations, any system installed prior to May 1995.
- (2) At the time of a Title 5 inspection risers will be added to bring the inlet and outlet covers to within 6” of grade.
 - (a) The addition of riser(s) will be noted on the state approved Title V Inspection Form.
- (3) At the time of a Title 5 Inspection a riser will be added to the D-Box to bring it within 6” of grade.
 - (a) The addition of riser(s) will be noted on the state approved Title V Inspection Form.
- (4) At the time of a Title 5 inspection a filter (Zabel 1800 or equivalent) will be added to the tank’s outlet tee.
 - (a) The addition of a filter will be noted on the state approved Title V Inspection Form.
- (5) The Inspection reports for systems with in 100 feet of the Monponsett Ponds or 200 feet of Silver Lake need to be further evaluated by the Board of Health or its Agent.
- (6) The inspector shall make reasonable professional efforts to locate and inspect all of the system components.
- (7) D-Box and/or Piping Repairs and Replacements:
 - (a) Any repair or replacement of a D-Box and/or piping found during a Title V Inspection, must be done by a permitted Septic Installer.
 - (b) Title V Inspectors can continue to do minor repairs such as filters and risers.
- (8) Orangeburg Piping:
 - (a) Back to the code book: Anything encountered not to code must be replaced.
 - (b) When a repair is needed on the D-Box and Orangeburg piping is found at a Title V Inspection:
 - i. Connecting the D-Box to the septic tank.

