Halifax Elementary School - Roof Project Punch List Items

an iter	The Punch List includes, but is not limited to, the following items. Additional items will be added to the list. The failure to m on the Punch List does not alter the responsibility of the Contractor to complete all work in accordance with the Contract			1				H&A 11-13-17
ents.	TASK	SOURCE	RESPONSIBLE PARTY	START DATE	COMPLETION	CONTRACTOR CHECK BY	H&A CHECK BY	Notes
					DATE	CHECK BY		
1	Provide loam for levelling damaged areas - plant grass seed. Install splash blocks below rain water leader outfall at several locations	H&A	Capeway					
	Provide elbows at bottom of rainwater leaders that spill onto sloped roofing at several locations.	H&A H&A	Capeway Capeway		1	ĺ	1	
			I		ı		I	
		1	1			1	ı	
		1	1	1	1	l .	1	
			1	1	1	1	1	
		į						
			1					
			1		ı	ĺ		
				_!		ļ.	l.	
	Paint white cast iron boot black to match others at new rainwater leader at main entrance to school.	H&A	Capeway				ļ	
	Fix misaligned roof hatch guard rail gate	H&A	Capeway		,			
	Finish installing walkway pads below rainwater leader outflows at area of Wing C. Finish stripping in PVC membrane to cover all failed PVC seams.	H&A H&A	Capeway Capeway	1	1			
8	Install uni-strut bracing at three tall PVC vent pipes on sloped roof of Area B.	H&A	Capeway					
					,			
		1	1	1	1			
				I	ı	l .	l .	
		1	1					
				_!	·	ļ.	l.	
			1	1	1	1	1	
			1	1	1	1	1	
			ı			I		
				1	1	ļ	ļ	
		1	ı	1	1	ı	ı	
9					· I	ļ	ļ	
		1		1	1	1	1	
	Remove temporary uni-strut at Reznor HVAC unit.	H&A	Capeway		ı		ļ	
		1	1	1	1		l	
			1					
				I		l .	l .	
	The second second	1	1					
				1	•		ı	
			1	1	1			
		1	ı	1	1	ı	ı	
		1	1	1	1	ı	ı	
			1-			•	•	
	Anchor condensing units to curb. Replace broken clapboard above flashing at Area B near Reznor HVAC unit.	H&A H&A	Capeway Capeway	1	1	ļ		
12	Provide weatherstripping and auto door bottom at new mechanical room door.	H&A	Capeway		1			
13	Provide aluminum clip angles for securing condening unit to new wood sleepers near mechanical room.	H&A	Capeway					
	Gas pipe supports need to be adjusted in several locations.	H&A	Capeway	1	1			
16	Increase size of roofing opening inside roof drain. Install missing walkway pads near library roof.	H&A H&A	Capeway		1	1	1	
17	Clean all debris from roof near RTU's behind library.	н&А	Capeway					
	Reattach heat trace cable at library roof.	H&A	Capeway		1			
	Install pipe caps at two abandoned roof drains. Refer to Russo Bar Punch List for additional items.	H&A	Capeway		1	l		
					1			
					1			
		1	1	1	1	ļ	L	
			_		1			
		1	1	1	1	I	L	
			1					
		1	1	1	1	I	l	
			1		1	1	1	
		1	1	1	1			
			1					1

Page 1 of 1 Printed on: 7/25/19, 10:11 AM