



HALIFAX HIGHWAY & CEMETERY
R. Steven Hayward
Highway Surveyor

60 Hemlock Lane
Halifax, MA 02338
Phone: 781-293-1760
Facsimile: 781-293-1762

Sorry I am unable to attend the meeting on 11/6/23 but here is some information from the Highway Department that was brought up last time they were going to ask for a permit.

Lingan St is 20' wide, the average semi-truck or school bus width is 8' to 9'. Here are some other neighborhoods as examples that have the same width road in town. Annawon Dr, Hemlock Ln, Hudson St, Ocean Ave.


I did have to scrape some sand and debris to measure from the edge of road but all the spots I checked where 20' to 20'3" wide there were also a couple homes that have paved in front of their house for parking that makes the road seem narrow because they are parking over or on the edge of the road.



Started 00.0




width 20'.3" I checked different spots on Lingan.



Parking right on edge of Lingan St.

over →

The only pipe issue the Highway Department has had on Lingan is old age, the drainage pipe had rotted at that time there was no hauling from the bog.



Before I started in this position I believe it was Morris or some one took pictures of foundations and bad sections of Lingan St. before the project started and after they were done with hauling they checked the before photos to how it looked after and surprisingly it was not as bad as we thought it would be. But we were going to Lingan st. more often to fill potholes. I would ask that any money that comes in from this permit go into a separate account set up for the extra cost of filling potholes or fixing Lingan at a later date or would the company be willing to help with the cost of fixing Lingan St.

Sincerely,

A handwritten signature in black ink that reads "Steve Hayward". The signature is fluid and cursive.

Steve Hayward
Halifax Highway Surveyor
Cemetery Superintendent
781-293-1760
Steve.Hayward@halifax-ma.org